Mysore District.

Subject and Name of Member introducing it.	Summary of discussion.	Reply of Govt.
Subject No. 404. **Reapirs to certain tanks in Gundlupet Taluk.** **Messrs Kotekere Bhujangaiya and Halehatti Venkata Setty of Gundlupet Taluk.**	The marginally noted five large tanks in the Taluk are out of order. The repair of Kempasagara tank seems to have been sanctioned. The Nallur tank has a large atchkat and occupies a central position. Its early repair is very necessary in the interests of Government and the raiyats. The necessity was brought to notice at the last meeting, when the representatives were informed that such works would be considered by and bye. No estimate seems to have as yet been framed for the repair of the tank. As the raiyats have suffered much loss in respect of dry crops for want of rain, it is requested that orders may be issued for the repair of this tank for the benefit of the raiyats. 1. Kodahallikere. 2. Kempasagarakere. 3. Nallurkere. 4. Hangaladahirekere. 5. Martipuradakere.	Referred to the D. P. W.
Subject No 405. **Repair of Bandikere tank in Chamrajnagar Taluk.** **Mr. Mallikarjunappa.**	The Bandikere tank in Chamrajnagar Taluk should be repaired.	Will be investigated by the D. P. W.
Subject No. 406. **Restoration of Umathur tank.** **Mr. Mallikarjunappa**	The Umathur tank is now out of order, notwithstanding its recent improvement at a large outlay of Rs. 24,000 defrayed from the temple funds. Its repair will cost over Rs. 12,000. It is requested that orders may be issued for spending such amount as is actually necessary to restore the tank to its original standard of safety.	The proposal will be investigated by the D. P. W.
Subject No. 407. **Repair of Bettahalli Tank in T. Narsipur Taluk.** **Mr. Srinivasiah.**	The Bettahalli tank breached 7 or 8 years ago, and the whole of its atchkat is lying waste, thus necessitating the remission of assessment annually. This tank can easily be fed by the waste weir water of the Bannur tank, and a large extent of land can thereby be brought under wet cultivation. The tank may be ordered to be repaired early.	Referred to the D. P. W.
Subject No. 408. **Restoration of Jagannatha's channel from the Madhav mantri anicut.** **Mr. Siddalinga Maridavaru.**	If the restoration by the British Government of Jagannatha's channel from the Madhvamantri anicut at Talkad cannot, as prayed for by the people of that place, be given up, it is requested that arrangements may be made for the work being so carried out as not to interfere with water-supply to the Madhvamantri channels	Do.